

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
18 BRS	500	(vehicle or van or car or automobile or auto-mobile or automotive or minivan or mini-van) and (door near10 (obstruct\$4 or obstacle)) and (sens\$4 or detect\$4) and (light or infrared or infra-red)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 20:17		
19 BRS	321	((vehicle or van or car or automobile or auto-mobile or automotive or minivan or mini-van) and (door near10 (obstruct\$4 or obstacle)) and (sens\$4 or detect\$4) and (light or infrared or infra-red)) and revers\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 20:04		
20 BRS	3	"06066065"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 19:12		
21 BRS	1	1994-115689.NRAN.	DERWENT	2004/01/28 19:13		
22 BRS	3	6304178.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 20:05		
23 BRS	80	(van or minivan or mini-van) and (door near10 (obstruct\$4 or obstacle)) and (sens\$4 or detect\$4) and (light or infrared or infra-red)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 22:40		
24 BRS	2	5845000.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 22:43		
25 BRS	3	"10205215"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 22:45		
26 BRS	1	1998-477742.NRAN.	DERWENT	2004/01/28 22:43		
27 BRS	2	"11200707"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/28 22:45		
28 BRS	2	"20010042820"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/29 11:59		
29 BRS	2	5142152.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/29 12:09		
30 BRS	2	6157024.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/01/29 12:09		